

Inspections: Damaged Pole Report

Service Request: 25-00446881 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2374 N. Fulton Ave
 Grid : 1020230 LLC: 7432

Descriptive Location and Comments:

Street: N. Fulton Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: Francis St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☒

11'6" _____

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ☒

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide ☒

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ☒

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:


Base Type:

Yes ☒
No ☒

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete ☒

Date: 5 / 30 / 2025 Inspector's Signature: G. Crowder 8512



2314 W. Fulton Ave
30 ft Ct
LED
400 Watts

Service Request Summary Report
25-00446881
Printed Date: Jun 3, 2025 - 3:42:43 PM

Type: BGE-StLight Pole Installation
Created By: Joseph Bullock
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00446881
Priority: Standard
Status: Pending
Status Date: Jun 03, 2025 3:39:51 PM
Created Date: May 28, 2025 7:44:08 PM
Overdue on: Jul 31, 2025 10:34:47 AM
Closed on:

Location: 2314 N FULTON AVE, Baltimore City,
21217

Location Details:

Description: N FULTON AVE & AUCHENTOROLY TER - vehicle accident debris

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/3/2025 3:40 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020230
Assign inspector	LLC / POLE #	7432
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete