

Inspections: Damaged Pole Report

Service Request: 25-00545225 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 100 Taplow Rd
 Grid : 1050140 LLC: 7022

Descriptive Location and Comments:

Street: Taplow Rd
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: N. Charles St

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland ☒
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA _____
 Otterbein _____
 Homeland ☒
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 7/16/2025 Inspector's Signature: G. Crowder 8512



100 Taplow Rd

1850140-7022

Service Request Summary Report
25-00545225
Printed Date: Jul 16, 2025 - 2:06:01 PM

Type: BGE-StLight Pole Installation
Created By: Karen Kendall
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 25-00545225
Priority: Urgent
Status: Pending
Status Date: Jul 16, 2025 2:03:36 PM
Created Date: Jun 28, 2025 8:45:11 AM
Overdue on: Sep 01, 2025 4:06:59 PM
Closed on:

Location: 100 TAPLOW RD, Baltimore City,
21212
Location Details:
Description: pole no is 7022

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
stewart koehler			+1 (410) 435-7233

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		7/16/2025 2:03 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1050140
Assign inspector	LLC / POLE #	7022
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Plc
Assign inspector	Type of Fixture	Homeland
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-7-16-25	Gregory Crowder	7/16/2025 2:05 PM	Private
Assign inspector : DPR Created By G Crowder-7-16-25	Gregory Crowder	7/16/2025 2:05 PM	Public