Inspections: Damaged Pole Report

Service Request: 25-00603073 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: W. Redwood St @ S. Eutaw St

Grid : 3010 140 LLC: 7443

Descriptive Location and Comments:

Street: S. Eutaw St

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ✓ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ✓ S/O _____ W/O _____

Street or Landmark: W. Redwood St

Condition of Pole:

Deteriorated _____
Missing _____
Damaged ✓
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' ✓
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein ✓
Homeland _____
Wooden _____
Other _____

Need new Concrete Base

Fixture Type:

Cobra Head _____
PMA _____
Otterbein ✓
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor ✓
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

Wattage:

100 _____
150 ✓
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:		Base Condition:	Good	Bad:	Base Type:	
Yes		Bolts	✓		Metal	
No	✓	Wires	✓		Concrete	✓
		Conduit	✓			

Date: 7/18/2025 Inspector's Signature G. Crowder - 8512



Redwood

Need new Concrete base

Otterbein Pole + Fixture

Pole pickup

Service Request Summary Report
25-00603073
Printed Date: Jul 18, 2025 - 1:23:57 PM

Type:	BGE-StLight Pole Installation	**SR #:**	25-00603073
Created By:	Ashley Sabb	**Prority:**	Urgent
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	Phone	**Status Date:**	Jul 18, 2025 1:20:34 PM
SLA Detail:	45 Business Days	**Created Date:**	Jul 17, 2025 7:15:19 AM
		Overdue on:	Sep 18, 2025 3:43:53 PM
		Closed on:	
Location:	W REDWOOD ST & S EUTAW ST, BC, 21201		
Location Details:			
Description:	blocking street,		

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		7/18/2025 1:20 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010140
Assign inspector	LLC / POLE #	7443
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Otterbein
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-7-18-25	Gregory Crowder	7/18/2025 1:22 PM	Private

Related Child Service Requests