

Inspections: Damaged Pole Report

Service Request: 25- 00800988 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 741 W. Cross St
 Grid : 3020110 LLC: 7117

Descriptive Location and Comments:

Street: Cross St
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: North Paca St

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 ☒
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒

Bad:

☐

Base Type:


Metal ☒
 Concrete _____

Date: 9/17/2025 Inspector's Signature: G. Crowder 8512

Need new base

There are
DOWNED
if you disc
electrical
please cal
the closes
NEVER TC

Pole Nui
30201107



251x04167

Service Request Summary Report
25-00800988
Printed Date: Sep 17, 2025 - 3:23:27 PM

Type: BGE-StLight Pole Installation
Created By: Richard Stewart
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00800988
Priority: Standard
Status: Pending
Status Date: Sep 17, 2025 3:12:52 PM
Created Date: Sep 16, 2025 2:11:14 PM
Overdue on: Nov 18, 2025 1:11:13 PM
Closed on:

Location: 741 W CROSS ST, Baltimore City,
21230

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		9/17/2025 3:21 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020110
Assign inspector	LLC / POLE #	7117
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created for pole installation By G Crowder-9-17-25	Gregory Crowder	9/17/2025 3:23 PM	Private
Assign inspector : DPR Created for pole installation By	Gregory Crowder	9/17/2025 3:23 PM	Public