

Inspections: Damaged Pole Report

Service Request: 25-00867206 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2636 Lehman St
 Grid : 3020320 LLC: 7018

Descriptive Location and Comments:

Street: Lehman St
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: East Lynne Ave

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" ☒
 12' _____
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ☒
 LED ☒
 Other City LED

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 10/9/2025 Inspector's Signature: G. Crowder 8512

There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES


If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-645-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

30203207018

REPORT THIS LIGHT



11'6 PMA City LED

Service Request Summary Report**25-00867206**

Printed Date: Oct 9, 2025 - 3:42:02 PM

Type: BGE-StLight Pole Installation
Created By: Shaquontai David
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00867206
Priority: Standard
Status: Pending
Status Date: Oct 09, 2025 3:40:15 PM
Created Date: Oct 07, 2025 3:11:19 PM
Overdue on: Dec 10, 2025 9:11:32 AM
Closed on:

Location: 2636 LEHMAN ST, Baltimore City,
21223

Location Details: Pole is at corner in front of address

Description: The entire pole is gone and there is a orange cone in place where the pole was in place at

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Refused Refused			

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		10/9/2025 3:40 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020320
Assign inspector	LLC / POLE #	7018
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-10-9-25	Gregory Crowder	10/9/2025 3:41 PM	Private

Related Child Service Requests