

already - BGE system

10-9-25

WO#

20509626

Inspections: Damaged Pole Report

Service Request: 25-00869484 Sector: _____ Gateway: _____ Primary: _____Location on Service Request: 4358 Old Frederick RdGrid : 3010430 LLC: 5006

Descriptive Location and Comments:

Street: Old Frederick RdSide of Street: N/S ☒ E/S _____ S/S _____ W/S _____Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____Direction : N/O _____ E/O _____ S/O _____ W/O ☒Street or Landmark: N. Athol Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ☒12' ☒

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland ☒

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor ☒100 ☒

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 ☒

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED _____

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn ☒

400 _____

Other _____

1000 _____

Pedestal Base:


Base Condition:

Good

Bad:

Base Type:

Yes ☒No ☒Bolts
Wires
Conduit☒
☒
☒☐
☐
☐Metal ☒
Concrete ☐Date: 10/10/2025 Inspector's Signature: G. Crowder 8512



12 ft Handland Area Fixtur

Service Request Summary Report
25-00869484
Printed Date: Oct 10, 2025 - 2:10:16 PM

Type: BGE-StLight Pole Installation
Created By: Karen Kendall
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00869484
Priority: Standard
Status: Pending
Status Date: Oct 10, 2025 1:55:59 PM
Created Date: Oct 08, 2025 11:53:49 AM
Overdue on: Dec 11, 2025 2:19:57 PM
Closed on:

Location: 4358 OLD FREDERICK RD, Baltimore City,
21229

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Chase Clark			+1 (240) 758-3257

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		10/10/2025 2:06 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010430
Assign inspector	LLC / POLE #	5006
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Plc
Assign inspector	Type of Fixture	Acorn
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created for pole installation By G Crowder-10-10-25	Gregory Crowder	10/10/2025 2:08 PM	Private