

Water Leak in front of the Water Meter at 711 Druid Hill Avenue

Photo 1: Fall sidewalk brick in front of 711 Druid Hill with a water in the opening of the brick. This is the second time this has happened with water in the area of the meter vault.



Photo 2: Another angle of the broken brick sidewalk with water in the vault of the water meter in front of 711 Druid Hill Avenue with water running in the street gutter.



Photo 3: Another picture of the broken sidewalk with water in the vault of the water meter at 711 Druid Hill Avenue. You can also see water running out of the drainage pipe of my entrance way.



Photo 4: Another angle of the broken sidewalk with water running out of the drainage pipe.



Pictures by: Dawnn McCleary, at 711 Druid Hill Avenue