

Inspections: Damaged Pole Report

Service Request: 25-00956644 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2353 Lauretta Ave
 Grid : 3010 320 LLC: 7132

Descriptive Location and Comments:

Street: W. heeler Ave
 Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Lauretta Ave

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" ☒
 12' _____
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 11/10/2025 Inspector's Signature: G. Crowder 8512



11'6 PMA LED

Service Request Summary Report
25-00956644
Printed Date: Nov 12, 2025 - 6:34:15 PM

Type: BGE-StLight Pole Installation
Created By: John Sills
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00956644
Priority: Standard
Status: Pending
Status Date: Nov 12, 2025 6:34:10 PM
Created Date: Nov 07, 2025 3:40:26 PM
Overdue on: Jan 14, 2026 3:45:16 PM
Closed on:

Location: 2353 LAURETTA AVE, Baltimore City, 21223
Location Details:
Description: street light down being struck by vehicle

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		11/12/2025 6:32 PM
Service Response	Not Started				

*11/10/25
Arson street light maintenance
Crew picked up pole*

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010320
Assign inspector	LLC / POLE #	7132
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created B y G Crowder 11-10-25	Gregory Crowder	11/12/2025 6:34 PM	Private

Related Child Service Requests