

Inspections: Damaged Pole Report

Sent to Chris
WO# 20604588

Service Request: 25-00963367 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 4200 Parkton St
Grid : 3020430 LLC: 7042

Descriptive Location and Comments:

Street: Parkton St
Side of Street: N/S _____ E/S ☒ S/S ☒ W/S _____
Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O ☒ S/O _____ W/O _____
Street or Landmark: Yale Ave

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" ☒
12' _____
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head _____
PMA ☒
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ☒
Other _____

Wattage:

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No _____

Base Condition:

Bolts _____
Wires _____
Conduit _____

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 11/14/2025 Inspector's Signature: G. Crowder 8512



Service Request Summary Report
25-00963367
Printed Date: Nov 14, 2025 - 3:41:08 PM

Type: BGE-StLight Pole Installation
Created By: Karen Kendall
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-00963367
Priority: Standard
Status: Pending
Status Date: Nov 14, 2025 3:39:47 PM
Created Date: Nov 11, 2025 7:37:20 AM
Overdue on: Jan 14, 2026 3:10:11 PM
Closed on:

Location: 4200 PARKTON ST, Baltimore City,
21229
Location Details:
Description: near the wooded area

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		11/14/2025 3:39 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020430
Assign inspector	LLC / POLE #	7042
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-11-14-25	Gregory Crowder	11/14/2025 3:41 PM	Private

Related Child Service Requests