

Inspections: Damaged Pole Report

Service Request: 25-01022544 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 6100 Walbark Ave

Grid : 1040510 LLC: 7134

Descriptive Location and Comments:

Street: Walbark AVE

Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒

Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th ☒ 6th _____ Other _____

Direction : N/O ☒ E/O _____ S/O _____ W/O _____

Street or Landmark: Int Hope DR

Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' _____

30' ☒

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____

No ☒

Base Condition:

Good

Bad:

Base Type:

Bolts ☒
Wires ☒
Conduit ☒

Metal ☒
Concrete ☒

Date: 12/8/2025 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
25-01022544
Printed Date: Dec 9, 2025 - 2:55:31 PM

Type: BGE-StLight Pole Installation
Created By: Jonai White
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-01022544
Priority: Standard
Status: Pending
Status Date: Dec 09, 2025 2:54:08 PM
Created Date: Dec 04, 2025 11:18:47 AM
Overdue on: Feb 06, 2026 1:55:40 PM
Closed on:

Location: 6100 WABASH AVE, Baltimore City,
21215
Location Details:
Description: pole was struck in accident- now damaged

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Mr Ron			+1 (301) 440-9693

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/9/2025 2:54 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1040510
Assign inspector	LLC / POLE #	7134
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : DPR Created By G Crowder-12-8-25	Gregory Crowder	12/9/2025 2:55 PM	Private

Related Child Service Requests
