

Inspections: Damaged Pole Report

Service Request: 25-01031381 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: E. Fort Ave w/ Woodall St
 Grid : 4020140 LLC: 7249

Descriptive Location and Comments:

Street: E. Fort Ave
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Woodall St

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing ☒
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Aluminum Fixture only

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 12/17/2025 Inspector's Signature: G. Crowder 8512

30 ft LED Pole Head
12/17/25
A&F only



Service Request Summary Report
25-01031381
Printed Date: Dec 17, 2025 - 11:09:49 AM

Type: BGE-StLight Pole Installation
Created By: Robin Gilliam
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-01031381
Priority: Standard
Status: Pending
Status Date: Dec 17, 2025 11:05:14 AM
Created Date: Dec 08, 2025 12:02:55 PM
Overdue on: Feb 10, 2026 4:31:50 PM
Closed on:

Location: E FORT AVE & WOODALL ST, Baltimore City,
21230

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Rachel Caruso		rcarusol14@gmail.com	+1 (410) 491-0229

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/10/2025 8:26 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	4020140
Assign inspector	LLC / POLE #	7249
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	Arm and fixture only
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Damaged Pole Report Created by G crowder12-17-25	Gregory Crowder	12/17/2025 11:08 AM	Private