

Inspections: Damaged Pole Report

Service Request: 25-01079371 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3203 W. North Ave
 Grid : 1010420 LLC: 5003

Descriptive Location and Comments:

Street: W North Ave
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O _____
 Street or Landmark: Hilton Pkwy

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" ☒
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland ☒
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn ☒
 Other _____

Lamp Type:

HPS Vapor ☒
 Mercury Vapor _____
 Metal Halide _____
 LED _____
 Other _____

Wattage:

100 ☒
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 12/23/2025 Inspector's Signature: G. Crowder 8512



Howland

12 Acres for sale

150 Watts

Service Request Summary Report
25-01075371

Printed Date: Dec 24, 2025 - 7:41:02 AM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-01075371
Priority: Standard
Status: Pending
Status Date: Dec 24, 2025 7:39:11 AM
Created Date: Dec 24, 2025 7:38:27 AM
Overdue on: Feb 25, 2026 7:38:27 AM
Closed on:

Location: 3203 W NORTH AVE, Baltimore City,
21216

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/24/2025 7:39 AM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010420
Assign inspector	LLC / POLE #	5003
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Ple
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report was created by G Crowder12-23-25	Gregory Crowder	12/24/2025 7:40 AM	Private
Assign inspector : missing pole report was created by G	Gregory Crowder	12/24/2025 7:40 AM	Public