

Inspections: Damaged Pole Report

Service Request: 25-01061978 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3202 W. North Ave
 Grid : 1010420 LLC: 7244

Descriptive Location and Comments:

Street: W. North Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: Bloomington Rd

Condition of Pole:

Deteriorated _____

Missing _____

Damaged ☒

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' _____

30' ☒

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new Pedestal Base

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good ☒

Bad: _____

Base Type:

Metal _____

Concrete ☒

Date: 12/23/2025 Inspector's Signature: G. Crowder 8512



30 ft CH LED
Pedestal Base

Service Request Summary Report**25-01061978**

Printed Date: Dec 24, 2025 - 7:37:25 AM

Type: BGE-StLight Pole Installation
Created By: Ashley Bailey
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 25-01061978
Priority: Standard
Status: Pending
Status Date: Dec 24, 2025 7:35:50 AM
Created Date: Dec 18, 2025 5:51:56 PM
Overdue on: Feb 20, 2026 1:58:43 PM
Closed on:

Location: 3202 W NORTH AVE, Baltimore City,
21216

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
mr stanley			+1 (410) 917-1286

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/24/2025 7:35 AM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010420
Assign inspector	LLC / POLE #	7244
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Pedestal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder	Gregory Crowder	12/24/2025 7:37 AM	Private
Assign inspector : missing pole report created by G	Gregory Crowder	12/24/2025 7:37 AM	Public