

Inspections: Damaged Pole Report

Service Request: 25-01071671 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 314 W. Hilton St
 Grid : 3010420 LLC: 7031/7032

Descriptive Location and Comments:

Street: N. Hilton St
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: N. Monastery Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Twin Mass
 ↓
Pedestal Base

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ☒
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____


Base Condition:

Good ☒
 Bad: _____
 Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal _____
 Concrete ☒

Date: 12/24/2025 Inspector's Signature: G. Crowder 8512



Twin Mass 30-ft Cora Head HPS

Service Request Summary Report**25-01071671**

Printed Date: Dec 24, 2025 - 10:54:59 AM

Type: BGE-StLight Pole Installation
Created By: Kira Huntley
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 25-01071671
Priority: Urgent
Status: Pending
Status Date: Dec 24, 2025 10:50:23 AM
Created Date: Dec 22, 2025 7:13:21 PM
Overdue on: Feb 24, 2026 3:26:56 PM
Closed on:

Location: 314 N HILTON ST, Baltimore City,
21229

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Anita Cathcart		allendalecomm@gmail.com	+1 (443) 827-1693

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/24/2025 10:50 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010420
Assign inspector	LLC / POLE #	7031/7032
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Pedestal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-12-24-25	Gregory Crowder	12/24/2025 10:54 AM	Private
Assign inspector : Twin mass pole needs new pedestal	Gregory Crowder	12/24/2025 10:54 AM	Public