

Inspections: Damaged Pole Report

Service Request: 25-108397 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 1250 Hull St

Grid : 4020 230 LLC: 7101

Descriptive Location and Comments:

Street: Beason St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Hull

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 ☒

250 _____

400 _____

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Bolts

Wires

Conduit

Good

☒

☒

☒


Bad:

Base Type:

Metal ☒

Concrete _____

Date: 12 / 31 / 2025 Inspector's Signature: G. Crowder - 8512



Service Request Summary Report
25-01084397
Printed Date: Dec 31, 2025 - 11:41:23 AM

Type: BGE-StLight Pole Installation
Created By: Ashley Sabb
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 25-01084397
Priority: Urgent
Status: Pending
Status Date: Dec 31, 2025 11:20:21 AM
Created Date: Dec 29, 2025 2:50:53 PM
Overdue on: Mar 03, 2026 3:35:51 PM
Closed on:

Location: 1250 HULL ST, Baltimore City,
21230

Location Details:
Description: blocking traffic

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/31/2025 11:25 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	4020230
Assign inspector	LLC / POLE #	7101
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created By G Crowder-12-31-25	Gregory Crowder	12/31/2025 11:26 AM	Private
Assign inspector : missing pole report created By G	Gregory Crowder	12/31/2025 11:26 AM	Public