Inspections: Damaged Pole Report

Service Request: 25-01084594 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: Pearl St & W. Lexington St

Grid : 3010120 LLC: 7594

Descriptive Location and Comments:

Street: Pearl St

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ✓ S/O _____ W/O _____

Street or Landmark: W. Lexington St

Condition of Pole:

- Deteriorated _____
- Missing ✓
- Damaged _____
- Arm/Fixture Missing _____
- Other _____

Pole Size :

- 11'6" _____
- 12' _____
- 25' ✓
- 30' _____
- 40' _____
- Other _____

Type of Pole:

- Aluminum ✓
- Steel _____
- Galvanized Steel _____
- Fiberglass _____
- Bolton Hill _____
- Otterbein _____
- Homeland _____
- Wooden _____
- Other _____

Need new base

Fixture Type:

- Cobra Head ✓
- PMA _____
- Otterbein _____
- Homeland _____
- Bolton Hill _____
- Victorian Acorn _____
- Other _____

Lamp Type:

- HPS Vapor _____
- Mercury Vapor _____
- Metal Halide ✓
- LED ✓
- Other _____

Wattage:

- 100 _____
- 150 _____
- 175 _____
- 200 _____
- 250 _____
- 400 ✓
- 1000 _____

Arm:

- 6' _____
- 10' _____
- 15' _____
- 20' _____
- Other _____

Arm Condition:

- Damaged _____
- Missing _____

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ✓	Bolts	✓	_____	Metal ✓
No _____	Wires	✓	_____	Concrete _____
	Conduit	✓	_____	

Date: 12/31/2025 Inspector's Signature G. Crowder 8512

W Lexington St
N Arch St
W Lexington St
Chicago Alley
Chicago Alley
Diamond St
W Lexington St
Shad St
N Greene St
Pearl St
N Arch St
W Fayette St
Fayette St
Diamond St
N Greene

ATTACHED

Service Request Summary Report
25-01084594
Printed Date: Dec 31, 2025 - 11:30:47 AM

Type:	BGE-StLight Pole Installation	**SR #:**	25-01084594
Created By:	citizen Site Guest User	**Prority:**	Standard
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	API	**Status Date:**	Dec 31, 2025 11:29:01 AM
SLA Detail:	45 Business Days	**Created Date:**	Dec 29, 2025 3:27:14 PM
		Overdue on:	Mar 03, 2026 3:34:04 PM
		Closed on:	
Location:	PEARL ST & W LEXINGTON ST, BC, 21201		
Location Details:			
Description:			

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions
Tanisha Diggs		tanishadiggs@police.umaryland.ed	+1 (410) 706-6882

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		12/31/2025 11:29 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010120
Assign inspector	LLC / POLE #	7594
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created By G Crowder-12-31-25	Gregory Crowder	12/31/2025 11:30 AM	Private
Assign inspector : missing pole report created By G	Gregory Crowder	12/31/2025 11:30 AM	Public