

A In BGE Sept
WO# 20778920

Inspections: Damaged Pole Report

Service Request: 26-00165515 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 2218 N. Monroe St
Grid : 1020 230 LLC: 7423

Descriptive Location and Comments:

Street: N. Monroe St
Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O _____ S/O ☒ W/O _____
Street or Landmark: ELGIN Ave

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' _____
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head ☒
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ☒
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ☒
1000 _____

Arm:

6' ☒
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Bolts _____
Wires _____
Conduit _____

Good

☒
☒
☒

Bad:

Base Type:

Metal _____
Concrete _____

Date: 2/17/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
26-00165515
Printed Date: Feb 17, 2026 - 3:26:23 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00165515
Priority: Standard
Status: Pending
Status Date: Feb 17, 2026 3:26:15 PM
Created Date: Feb 17, 2026 3:22:40 PM
Overdue on: Apr 21, 2026 4:22:40 PM
Closed on:

Location: 2218 N MONROE ST, Baltimore City,
21217

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/17/2026 3:23 PM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020230
Assign inspector	LLC / POLE #	7423
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-2-17-26	Gregory Crowder	2/17/2026 3:26 PM	Private

