

Inspections: Damaged Pole Report

Service Request: 26-00147126 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 227 W. Lexington St

Grid : 3010120 LLC: 6385

Descriptive Location and Comments:

Street: W. Lexington St

Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____

Pole location: 1st _____ 2nd _____ 3rd ☒ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Howard St

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum _____
Missing ☒	12' ☒	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein ☒
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head _____	HPS Vapor ☒	100 _____	6' _____	Damaged _____
PMA _____	Mercury Vapor _____	150 ☒	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED _____	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn ☒		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete ☒
	Conduit ☒	☒	_____	

Date: 2/17/2026 Inspector's Signature: G. Crowder 8512

Lexington Market
Light Rail Station



Service Request Summary Report
26-00147126
Printed Date: Feb 17, 2026 - 4:06:07 PM

Type: BGE-StLight Pole Installation
Created By: Nathan Tarter
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00147126
Priority: Standard
Status: Pending
Status Date: Feb 17, 2026 4:00:26 PM
Created Date: Feb 12, 2026 9:49:51 AM
Overdue on: Apr 17, 2026 10:39:46 AM
Closed on:

Location: 227 W LEXINGTON ST, Baltimore City,
21201

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
nathian carter		ntarter15@gmail.com	+1 (443) 220-8015

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/17/2026 4:04 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010120
Assign inspector	LLC / POLE #	6385
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created -2-17-26	Gregory Crowder	2/17/2026 4:06 PM	Private

Related Child Service Requests