

Inspections: Damaged Pole Report

Service Request: 26-00155510 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3010 Evergreen Ave

Grid : 2040 320 LLC: 7170

Descriptive Location and Comments:

Street: Evergreen Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Richard Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head _____

PMA ☒

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No ☒

Base Condition:

Bolts ☒

Wires ☒

Conduit ☒

Good

☒

☒

☒

Bad:

Base Type:

Metal ☒

Concrete _____

Date: 2/18/2026 Inspector's Signature: G. Crowder 8512



12th PMA

Service Request Summary Report
26-00155510
Printed Date: Feb 18, 2026 - 3:00:38 PM

Type: BGE-StLight Pole Installation
Created By: Sharon B
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00155510
Priority: Standard
Status: Pending
Status Date: Feb 18, 2026 2:58:07 PM
Created Date: Feb 14, 2026 9:53:53 AM
Overdue on: Apr 22, 2026 9:09:09 AM
Closed on:

Location: 3010 EVERGREEN AVE, Baltimore City, 21214
Location Details: Light post leaning from when the snow contractors pushed the snow against the pole to create an 8 ft mountain.
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
ms bumbray		msholt10@yahoo.com	+1 (443) 680-3693

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/18/2026 2:58 PM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	2040320
Assign inspector	LLC / POLE #	7170
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-2-18-26	Gregory Crowder	2/18/2026 3:00 PM	Private