

Atkedy in Synter BGE
WO# 20785128

Inspections: Damaged Pole Report

Service Request: 26-00157500 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 516 N. Charles St
Grid : 4010110 LLC: 6492

Descriptive Location and Comments:

Street: N. Charles St
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O _____ S/O _____ W/O ☒
Street or Landmark: W. Hamilton St

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' ☒

25' _____

30' _____

40' _____

Other _____

Type of Pole:

Aluminum _____

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein ☒

Homeland _____

Wooden _____

Other _____

Fixture Type:

Cobra Head _____

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn ☒

Other _____

Lamp Type:

HPS Vapor ☒

Mercury Vapor _____

Metal Halide _____

LED _____

Other _____

Wattage:

100 _____

150 ☒

175 _____

200 _____

250 _____

400 _____

1000 _____

Arm:

6' _____

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition: Good _____

Bolts ☒
Wires ☒
Conduit ☒

Bad: _____

Base Type:

Metal ☒
Concrete _____

Date: 2/19/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report**26-00157500**

Printed Date: Feb 19, 2026 - 3:01:48 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00157500
Priority: Urgent
Status: Pending
Status Date: Feb 19, 2026 3:01:39 PM
Created Date: Feb 15, 2026 9:58:33 AM
Overdue on: Apr 22, 2026 4:22:46 PM
Closed on:

Location: 516 N CHARLES ST, Baltimore City,
21201

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Downtown PARTNERSHIP

+1 (410) 802-9631

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/19/2026 2:59 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	4010110
Assign inspector	LLC / POLE #	6492
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder 2-19-26	Gregory Crowder	2/19/2026 3:01 PM	Private

