

Inspections: Damaged Pole Report

Service Request: 26-00177216 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3752 W. Belvedere Ave
 Grid : 1040 430 LLC: 7349

Descriptive Location and Comments:

Street: W. Belvedere Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: Cordelia Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide ☒	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒
 No ☒

Bolts ☒
 Wires ☒
 Conduit ☒

Metal ☒
 Concrete ☒

Date: 2/26/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
26-00177216
Printed Date: Feb 25, 2026 - 3:42:31 PM

Type: BGE-StLight Pole Installation
Created By: Rasheeda Jones
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00177216
Priority: Urgent
Status: Open
Status Date: Feb 25, 2026 3:34:40 PM
Created Date: Feb 20, 2026 10:55:36 AM
Overdue on: Apr 28, 2026 4:43:01 PM
Closed on:

Location: 3752 W BELVEDERE AVE, Baltimore City, 21215

Location Details:

Description: AT THE BUS STOP A DRUNK DRIVER KNOCKED THE STREET LIGHT POLE DOWN
SENSE OCT

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
GENE WILLIAMS			+1 (667) 213-7503

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/25/2026 3:34 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1040430
Assign inspector	LLC / POLE #	7349
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report Created by G Crowder-2-25-26	Gregory Crowder	2/25/2026 3:37 PM	Private