

# Inspections: Damaged Pole Report

Service Request: 26-00179282 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_

Location on Service Request: 612 St Johns Rd

Grid: 1040110 LLC: 7147

## Descriptive Location and Comments:

Street: St Johns Rd

Side of Street: N/S ☒ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_

Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> ☒ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_

Direction: N/O \_\_\_\_\_ E/O ☒ S/O \_\_\_\_\_ W/O \_\_\_\_\_

Street or Landmark: Summit

## Condition of Pole:

Deteriorated ☒

Missing ☒

Damaged \_\_\_\_\_

Arm/Fixture Missing \_\_\_\_\_

Other \_\_\_\_\_

## Pole Size:

11'6" ☒

12' ☒

25' \_\_\_\_\_

30' \_\_\_\_\_

40' \_\_\_\_\_

Other \_\_\_\_\_

## Type of Pole:

Aluminum ☒

Steel \_\_\_\_\_

Galvanized Steel \_\_\_\_\_

Fiberglass \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Wooden \_\_\_\_\_

Other \_\_\_\_\_

Need new base

## Fixture Type:

Cobra Head \_\_\_\_\_

PMA ☒

Otterbein \_\_\_\_\_

Homeland \_\_\_\_\_

Bolton Hill \_\_\_\_\_

Victorian Acorn \_\_\_\_\_

Other \_\_\_\_\_

## Lamp Type:

HPS Vapor ☒

Mercury Vapor \_\_\_\_\_

Metal Halide \_\_\_\_\_

LED \_\_\_\_\_

Other \_\_\_\_\_

## Wattage:

100 ☒

150 ☒

175 \_\_\_\_\_

200 \_\_\_\_\_

250 \_\_\_\_\_

400 \_\_\_\_\_

1000 \_\_\_\_\_

## Arm:

6' \_\_\_\_\_

10' \_\_\_\_\_

15' \_\_\_\_\_

20' \_\_\_\_\_

Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_

Missing \_\_\_\_\_

## Pedestal Base:

Yes ☒

No \_\_\_\_\_

## Base Condition:

Good ☒

Bad: \_\_\_\_\_

Bolts ☒

Wires ☒


Conduit ☒

## Base Type:

Metal ☒

Concrete \_\_\_\_\_

Date: 2/25/2026 Inspector's Signature: J. Crowder 8512



17th PMA

**Service Request Summary Report**  
**26-00179282**  
Printed Date: Feb 25, 2026 - 3:50:26 PM

**Type:** BGE-StLight Pole Installation  
**Created By:** Tahsen Carr  
**Service Request Owner:** BGE  
**Method Received:** Internal  
**SLA Detail:** 45 Business Days

**SR #:** 26-00179282  
**Priority:** Standard  
**Status:** Pending  
**Status Date:** Feb 25, 2026 3:47:28 PM  
**Created Date:** Feb 20, 2026 3:59:56 PM  
**Overdue on:** Apr 28, 2026 4:44:14 PM  
**Closed on:**

**Location:** 612 SAINT JOHNS RD, Baltimore City,  
21210

**Location Details:**  
**Description:**

**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name           | Address | Email                    | Phones/Extensions |
|----------------|---------|--------------------------|-------------------|
| Rebecca Waring |         | rebeccawaring6@gmail.com | +1 (410) 262-8103 |

**Service Activities**

| Activity Name    | Status      | Assigned To     | Outcome  | Outcome Reason | Finish Date       |
|------------------|-------------|-----------------|----------|----------------|-------------------|
| Assign inspector | Complete    | Gregory Crowder | Assigned |                | 2/25/2026 3:47 PM |
| Service Response | Not Started |                 |          |                |                   |

**Resolution Questions**

| Service Activity | Resolution Question       | Resolution Answer         |
|------------------|---------------------------|---------------------------|
| Assign inspector | GRID #                    | 1040110                   |
| Assign inspector | LLC / POLE #              | 7147                      |
| Assign inspector | BGE AS8 Work Order Number |                           |
| Assign inspector | BCRL #                    |                           |
| Assign inspector | BCRL Created date         |                           |
| Assign inspector | Pole type                 | 12 ft Steel/Aluminum Pole |
| Assign inspector | Type of Fixture           | PMA                       |
| Assign inspector | Wattage of the Fixture    | 150 Watts                 |
| Assign inspector | Base type                 | Metal                     |

**Comments**

| Comment                                                             | Comment By      | Created Date      | Visibility |
|---------------------------------------------------------------------|-----------------|-------------------|------------|
| Assign inspector : missing pole report created by G Crowder-2-25-26 | Gregory Crowder | 2/25/2026 3:50 PM | Private    |