

Inspections: Damaged Pole Report

Service Request: 26-00198554 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2810 W. Franklin St

Grid : 3010 310 LLC: 7212

Descriptive Location and Comments:

Street: W. Franklin St

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th ☒ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ☒

Street or Landmark: Franklin St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated ☒ 11'6" _____

Aluminum ☒

Missing ☒ 12' _____

Steel _____

Damaged _____ 25' _____

Galvanized Steel _____

Arm/Fixture Missing ☒ 30' ☒

Fiberglass _____

Other _____ 40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒ HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____ Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____ Metal Halide _____

175 _____

15' _____

Homeland _____ LED ☒

200 _____

20' _____

Bolton Hill _____ Other _____

250 _____

Other _____

Victorian Acorn _____

400 ☒

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes ☒
No ☒

Bolts
Wires
Conduit

☒
☒
☒

Metal ☒
Concrete ☒

Date: 2/26/2026 Inspector's Signature: G. Crowder 8512



30-ACH LED

Service Request Summary Report
26-00054236
Printed Date: Feb 26, 2026 - 3:30:46 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00054236
Priority: Standard
Status: Pending
Status Date: Jan 21, 2026 3:16:23 PM
Created Date: Jan 21, 2026 2:28:57 PM
Overdue on: Mar 25, 2026 3:28:57 PM
Closed on:

Location: 2810 W FRANKLIN ST, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		1/21/2026 2:30 PM

Service Response Not Started

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010310
Assign inspector	LLC / POLE #	7210
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder 1-21-26	Gregory Crowder	1/21/2026 2:32 PM	Private