

Inspections: Damaged Pole Report

Service Request: 26- 60167300 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 3832 PARK Hgts Ave
 Grid : 1030 340 LLC: 7266

Descriptive Location and Comments:

Street: PARK Hgts Ave
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O _____
 Street or Landmark: Keyworth Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' _____
 30' ☒
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ☒
 LED _____
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 2/26/2026 Inspector's Signature: J. Crowder 8512



3047CH LED

Service Request Summary Report
26-00187300
Printed Date: Feb 26, 2026 - 3:08:47 PM

Type: BGE-StLight Pole Installation
Created By: Patricia Jones
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00187300
Priority: Urgent
Status: Pending
Status Date: Feb 26, 2026 3:06:41 PM
Created Date: Feb 23, 2026 7:10:24 PM
Overdue on: Apr 29, 2026 4:17:42 PM
Closed on:

Location: 3832 PARK HEIGHTS AVE, Baltimore City, 21215
Location Details:
Description: pole down on the sidewalk

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
wanda cofield			+1 (443) 762-5488

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/26/2026 3:06 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030340
Assign inspector	LLC / POLE #	7206
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Service Response : New Comment was added in Destination System: A. Burley picked up 30' pole BGE needs to reinstall	citizen Site Guest User	2/25/2026 3:13 PM	Private