

Inspections: Damaged Pole Report

Service Request: 26-00191779 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2480 Francis St
 Grid: 1020240 LLC: 7033

Descriptive Location and Comments:

Street: Francis St
 Side of Street: N/S _____ E/S ☒ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O ☒ W/O _____
 Street or Landmark: Retreat St

Condition of Pole:

Deteriorated ☒
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 _____
 175 _____
 200 _____
 250 _____
 400 ☒
 1000 _____

Arm:

6' ☒
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No _____


Base Condition:

Good ☒
 Bad: _____
 Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal ☒
 Concrete _____

Date: 2/26/2026 Inspector's Signature: G. Crowder 8512



25th CHLED

Service Request Summary Report
26-00191779
Printed Date: Feb 26, 2026 - 3:29:44 PM

Type: BGE-StLight Pole Installation
Created By: Leslie Williams
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00191779
Priority: Urgent
Status: Pending
Status Date: Feb 26, 2026 3:29:38 PM
Created Date: Feb 24, 2026 10:53:58 PM
Overdue on: Apr 29, 2026 4:15:33 PM
Closed on:

Location: 2480 FRANCIS ST, BC,
21217
Location Details:
Description: CAD #50053

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/26/2026 3:13 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020240
Assign inspector	LLC / POLE #	7033
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report Created By G Crowder-2-26-26	Gregory Crowder	2/26/2026 3:16 PM	Private