

Inspections: Damaged Pole Report

Service Request: 26-00179169 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: Garrison Blvd at Wabash Ave

Grid : 1636 410 LLC: 7362

Descriptive Location and Comments:

Street: Wabash Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd _____ 3rd _____ 4th ☒ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: Garrison Blvd

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' ☒
30' ☒
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Cobra Head ☒
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide ☒
LED ☒
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ☒
1000 _____

Arm:

6' ☒
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Good ☒ Bad: _____
Bolts ☒
Wires ☒
Conduit ☒

Base Type:

Metal ☒
Concrete ☒

Date: 2/26/2026 Inspector's Signature: G. Crowder 8512



30 ft CH LED

Service Request Summary Report
26-00179169
Printed Date: Feb 26, 2026 - 2:54:12 PM

Type: BGE-StLight Pole Installation
Created By: Nicole Phillips
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00179169
Priority: Urgent
Status: Pending
Status Date: Feb 26, 2026 2:46:19 PM
Created Date: Feb 20, 2026 3:38:28 PM
Overdue on: Apr 29, 2026 4:17:10 PM
Closed on:

Location: GARRISON BLVD & WABASH AVE, Baltimore City, 21215

Location Details:
Description: THERE WAS AN ACCIDENT AT THE INTERSECTION

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
MALE CALLER			+1 (443) 835-7502

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		2/26/2026 2:46 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030410
Assign inspector	LLC / POLE #	7362
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created G Crowder-2-26-26	Gregory Crowder	2/26/2026 2:54 PM	Private