

Inspections: Damaged Pole Report

Service Request: 26-00221705 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 5601 Belle Ave
 Grid : 1030 510 LLC: 7066

Descriptive Location and Comments:

Street: Bowers Ave
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Belle Ave

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Need new base

Fixture Type:

Cobra Head _____
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 ☒
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒


Base Condition:

Good ☒
 Bad: _____
 Bolts ☒
 Wires ☒
 Conduit ☒

Base Type:

Metal ☒
 Concrete _____

Date: 3/10/2026 Inspector's Signature: G. Crowder 8512



Service Request Summary Report
26-00221705
Printed Date: Mar 10, 2026 - 1:51:55 PM

Type: BGE-StLight Pole Installation
Created By: Jonathan Williams
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00221705
Priority: Urgent
Status: Pending
Status Date: Mar 10, 2026 1:50:47 PM
Created Date: Mar 06, 2026 10:46:09 AM
Overdue on: May 11, 2026 3:41:19 PM
Closed on:

Location: 5601 BELLE AVE, Baltimore City,
21207

Location Details:
Description: leaning light pole

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Mabel Palmer		mabel99@msn.com	+1 (410) 367-5051

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/10/2026 1:50 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030510
Assign inspector	LLC / POLE #	7066
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-3-10-26	Gregory Crowder	3/10/2026 1:51 PM	Private