Inspections: Damaged Pole Report

Service Request: 26-00221907 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3900 Dorchester Rd

Grid : 1030430 LLC: 7110

Descriptive Location and Comments:

Street: Dorchester Rd

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: Garrison Blvd

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ✓
Missing ✓	12' ✓	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Need new base

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head _____	HPS Vapor _____	100 _____	6' _____	Damaged _____
PMA ✓	Mercury Vapor _____	150 ✓	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ✓	200 _____	20' _____	
Bolton Hill _____	Other City LED	250 _____	Other _____	
Victorian Acorn _____		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts	✓	_____	Metal ✓
No ✓	Wires	✓	_____	Concrete _____
	Conduit	✓	_____	

Date: 3/10/2026 Inspector's Signature G. Crowder 8512

12 ft CH City LED

Service Request Summary Report
26-00221907
Printed Date: Mar 10, 2026 - 1:44:29 PM

Type:	BGE-StLight Pole Installation	**SR #:**	26-00221907
Created By:	Robin Gilliam	**Prority:**	Standard
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	Internal	**Status Date:**	Mar 10, 2026 1:42:43 PM
SLA Detail:	45 Business Days	**Created Date:**	Mar 06, 2026 11:26:57 AM
		Overdue on:	May 11, 2026 3:42:15 PM
		Closed on:	
Location:	3900 DORCHESTER RD, Baltimore City, 21207		
Location Details:			
Description:			

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions
BRENDA GLADDEN		gladdenbrenda4@gmail.com	+1 (443) 991-1419

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/10/2026 1:42 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1030430
Assign inspector	LLC / POLE #	7110
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-3-10-26	Gregory Crowder	3/10/2026 1:44 PM	Private