

Inspections: Damaged Pole Report

Service Request: 26-00245107 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_  
 Location on Service Request: Dolphin St @ Bolton St  
 Grid: 1010140 LLC: 7486

Descriptive Location and Comments:

Street: Bolton St  
 Side of Street: N/S \_\_\_\_\_ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S ☒  
 Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_  
 Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O ☒ W/O \_\_\_\_\_  
 Street or Landmark: Dolphin St


| Condition of Pole:                          | Pole Size:                              | Type of Pole:                                |
|---------------------------------------------|-----------------------------------------|----------------------------------------------|
| Deteriorated _____                          | 11'6" _____                             | Aluminum <input checked="" type="checkbox"/> |
| Missing <input checked="" type="checkbox"/> | 12' _____                               | Steel _____                                  |
| Damaged _____                               | 25' _____                               | Galvanized Steel _____                       |
| Arm/Fixture Missing _____                   | 30' <input checked="" type="checkbox"/> | Fiberglass _____                             |
| Other _____                                 | 40' _____                               | Bolton Hill _____                            |
|                                             | Other _____                             | Otterbein _____                              |
|                                             |                                         | Homeland _____                               |
|                                             |                                         | Wooden _____                                 |
|                                             |                                         | Other _____                                  |

Need new Pedestal Base

| Fixture Type:                                  | Lamp Type:                              | Wattage:                                | Arm:        | Arm Condition: |
|------------------------------------------------|-----------------------------------------|-----------------------------------------|-------------|----------------|
| Cobra Head <input checked="" type="checkbox"/> | HPS Vapor _____                         | 100 _____                               | 6' _____    | Damaged _____  |
| PMA _____                                      | Mercury Vapor _____                     | 150 _____                               | 10' _____   | Missing _____  |
| Otterbein _____                                | Metal Halide _____                      | 175 _____                               | 15' _____   |                |
| Homeland _____                                 | LED <input checked="" type="checkbox"/> | 200 _____                               | 20' _____   |                |
| Bolton Hill _____                              | Other _____                             | 250 _____                               | Other _____ |                |
| Victorian Acorn _____                          |                                         | 400 <input checked="" type="checkbox"/> |             |                |
| Other _____                                    |                                         | 1000 _____                              |             |                |

| Pedestal Base:                          | Base Condition:                             | Good | Bad: | Base Type:                                |
|-----------------------------------------|---------------------------------------------|------|------|-------------------------------------------|
| Yes <input checked="" type="checkbox"/> | Bolts <input checked="" type="checkbox"/>   |      |      | Metal <input checked="" type="checkbox"/> |
| No _____                                | Wires <input checked="" type="checkbox"/>   |      |      | Concrete _____                            |
|                                         | Conduit <input checked="" type="checkbox"/> |      |      |                                           |

Date: 3/17/2026 Inspector's Signature: G. Crowder 8512



1100 Bolton St

**Service Request Summary Report****26-00245107**

Printed Date: Mar 17, 2026 - 11:23:37 AM

**Type:** BGE-StLight Pole Installation  
**Created By:** Adrienne Coner  
**Service Request Owner:** BGE  
**Method Received:** Phone  
**SLA Detail:** 45 Business Days

**SR #:** 26-00245107  
**Priority:** Urgent  
**Status:** Pending  
**Status Date:** Mar 17, 2026 11:23:30 AM  
**Created Date:** Mar 13, 2026 5:10:25 PM  
**Overdue on:** May 18, 2026 1:18:02 PM  
**Closed on:**

**Location:** DOLPHIN ST & BOLTON ST, BC,  
21201

**Location Details:****Description:** blocking street**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name           | Address | Email | Phones/Extensions |
|----------------|---------|-------|-------------------|
| lynette knight |         |       | +1 (410) 805-3345 |

**Service Activities**

| Activity Name    | Status      | Assigned To     | Outcome  | Outcome Reason | Finish Date        |
|------------------|-------------|-----------------|----------|----------------|--------------------|
| Assign inspector | Complete    | Gregory Crowder | Assigned |                | 3/17/2026 11:19 AM |
| Service Response | Not Started |                 |          |                |                    |

**Resolution Questions**

| Service Activity | Resolution Question       | Resolution Answer   |
|------------------|---------------------------|---------------------|
| Assign inspector | GRID #                    | 1010140             |
| Assign inspector | LLC / POLE #              | 7486                |
| Assign inspector | BGE AS8 Work Order Number |                     |
| Assign inspector | BCRL #                    |                     |
| Assign inspector | BCRL Created date         |                     |
| Assign inspector | Pole type                 | 30 ft Aluminum Pole |
| Assign inspector | Type of Fixture           | Cobrahead           |
| Assign inspector | Wattage of the Fixture    | 400 Watts           |
| Assign inspector | Base type                 | Pedestal            |

**Comments**

| Comment                                                             | Comment By      | Created Date       | Visibility |
|---------------------------------------------------------------------|-----------------|--------------------|------------|
| Assign inspector : missing pole report created by G Crowder-3-17-26 | Gregory Crowder | 3/17/2026 11:20 AM | Private    |