

Inspections: Damaged Pole Report

Service Request: 26-00248202 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 1 W. Sanatoga Mt
 Grid: 3010120 LLC: 6412

Descriptive Location and Comments:

Street: W. Sanatoga Mt
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction: N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: N. Charles Mt

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size:

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum _____
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein ☒
 Homeland _____
 Wooden _____
 Other _____

Fixture Type:

Cobra Head _____
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn ☒
 Other _____

Lamp Type:

HPS Vapor ☒
 Mercury Vapor _____
 Metal Halide _____
 LED _____
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes ☒
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good

☒
☒
☒


Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 3/17/2025 Inspector's Signature: G. Crowder 8512

W. CHARLES ST



Service Request Summary Report
26-00248202
Printed Date: Mar 18, 2026 - 1:53:37 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00248202
Priority: Standard
Status: Pending
Status Date: Mar 18, 2026 1:53:23 PM
Created Date: Mar 15, 2026 11:29:04 AM
Overdue on: May 18, 2026 12:58:50 PM
Closed on:

Location: 1 BLK W SARATOGA ST, Baltimore City,
21201
Location Details:
Description: Pole down

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Downtown Partnership			+1 (

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/18/2026 1:51 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010120
Assign inspector	LLC / POLE #	6412
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Otterbein Pole
Assign inspector	Type of Fixture	Acorn
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-3-17-26	Gregory Crowder	3/18/2026 1:53 PM	Private