

Inspections: Damaged Pole Report

Service Request: 26-00277068 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 1300 W. Lafayette Ave
 Grid : 1010240 LLC: 7392

Descriptive Location and Comments:

Street: N. Carey St
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: W. Lafayette Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

11'6" _____
 12' _____
 25' ☒
 30' _____
 40' _____
 Other _____

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Need new
base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒
 PMA _____
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide ☒
 LED ☒
 Other _____

100 _____
 150 _____
 175 _____
 200 _____
 250 ☒
 400 ☒
 1000 _____

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Damaged _____
 Missing _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes ☒
 No ☒

Bolts
 Wires
 Conduit

☒
☒
☒

Metal ☒
 Concrete _____

Date: 3/24/2025 Inspector's Signature: G. Crowder 8512



25 ft CH LED

Service Request Summary Report
26-00277068
Printed Date: Mar 24, 2026 - 2:25:01 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00277068
Priority: Standard
Status: Pending
Status Date: Mar 24, 2026 2:24:53 PM
Created Date: Mar 24, 2026 2:22:45 PM
Overdue on: May 26, 2026 2:22:44 PM
Closed on:

Location: 1300 W LAFAYETTE AVE, Baltimore City,
21217
Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
------	---------	-------	-------------------

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/24/2026 2:23 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010240
Assign inspector	LLC / POLE #	7392
Assign inspector	BGE AS\$ Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-3-24-26	Gregory Crowder	3/24/2026 2:24 PM	Private