Waiting on Chris

Inspections: Damaged Pole Report

Service Request: 26-00283286 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2201 McCulloh St

Grid : 1010220 LLC: 7478

Descriptive Location and Comments:

Street: McCulloh St

Side of Street: N/S ✓ E/S _____ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O _____ S/O _____ W/O ✓

Street or Landmark: Gold St

Condition of Pole:

Deteriorated _____
Missing _____
Damaged _____
Arm/Fixture Missing ✓
Other _____

Pole Size :

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

A+F only

Fixture Type:

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ✓
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ✓
1000 _____

Arm:

6' ✓
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing ✓

Pedestal Base:

Yes _____
No ✓


Base Condition:

	Good	Bad:
Bolts	✓	_____
Wires	✓	_____
Conduit	✓	_____

Base Type:

Metal ✓
Concrete _____

Date: 3/25/2026 Inspector's Signature G. Crowder 8512



2201 McCulloh St ArcFinder

Service Request Summary Report
26-00283286
Printed Date: Mar 26, 2026 - 10:45:52 AM

Type:	BGE-StLight Pole Installation	**SR #:**	26-00283286
Created By:	Gregory Crowder	**Prority:**	Standard
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	Internal	**Status Date:**	Mar 26, 2026 10:42:37 AM
SLA Detail:	45 Business Days	**Created Date:**	Mar 26, 2026 10:41:59 AM
		Overdue on:	May 28, 2026 10:41:59 AM
		Closed on:	
Location:	2201 MCCULLOH ST, BC, 21217		
Location Details:			
Description:			

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		3/26/2026 10:42 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010220
Assign inspector	LLC / POLE #	7478
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	Arm and fixture only
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created Arm & Fixture Only missing	Gregory Crowder	3/26/2026 10:45 AM	Private