Inspections: Damaged Pole Report

Service Request: 26-00334355 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: Baker St @ Pennsylvania Ave

Grid : 1010 220 LLC: 7546

Descriptive Location and Comments:

Street: Pennsylvania Ave

Side of Street: N/S _____ E/S ✓ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O ✓ E/O _____ S/O _____ W/O _____

Street or Landmark: Baker St

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ✓
Missing ✓	12' _____	Steel _____
Damaged _____	25' ✓	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ✓	HPS Vapor _____	100 _____	6' ✓	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ✓	200 _____	20' _____	
Bolton Hill _____	Other _____	250 ✓	Other _____	
Victorian Acorn _____		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts	✓	_____	Metal ✓
No ✓	Wires	✓	_____	Concrete _____
	Conduit	✓	_____	

Date: 4/14/2026 Inspector's Signature G. Crowder 8512


Senker Pl
Pennsylvania Ave
Baker St
Baker St
Pennsylvania Ave

Service Request Summary Report
26-00334355
Printed Date: Apr 14, 2026 - 3:36:03 PM

Type:	BGE-StLight Pole Installation	**SR #:**	26-00334355
Created By:	Ashley Sabb	**Prority:**	Urgent
Service Request Owner:	BGE	**Status:**	Pending
Method Received:	Phone	**Status Date:**	Apr 14, 2026 3:34:16 PM
SLA Detail:	45 Business Days	**Created Date:**	Apr 12, 2026 12:38:33 PM
		Overdue on:	Jun 15, 2026 3:44:42 PM
		Closed on:	
Location:	BAKER ST & PENNSYLVANIA AVE, Baltimore City, 21217		
Location Details:			
Description:			

Service Questions

Questions	Answers

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		4/14/2026 3:34 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010220
Assign inspector	LLC / POLE #	7546
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-4-14-26	Gregory Crowder	4/14/2026 3:35 PM	Private