

Wot Alkedia System
2050 9656

Inspections: Damaged Pole Report

Service Request: 26-00397917 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 2934 Stranden Rd
Grid: 3040210 LLC: 7136

Descriptive Location and Comments:

Street: Stranden Rd
Side of Street: N/S _____ E/S ☒ S/S _____ W/S _____
Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction: N/O _____ E/O _____ S/O ☒ W/O _____
Street or Landmark: Wegworth Ln

Condition of Pole:	Pole Size:	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' ☒	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Need new base

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head _____	HPS Vapor _____	100 _____	6' _____	Damaged _____
PMA ☒	Mercury Vapor _____	150 ☒	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes _____	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 4/30/2026 Inspector's Signature: G. Crowder 8512



2934 STRANDEN Rd

We are aware of a problem on this streetlight.

Status:

Pending Repair

Pole Number:

30402107136

Order Number:

20509656

Date Reported:

10/9/2025 4:49 PM EDT

Estimated Time of Repair:

11/04/2025

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-601-23** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Service Request Summary Report**26-00397917**

Printed Date: Apr 30, 2026 - 2:04:09 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00397917
Priority: Standard
Status: Pending
Status Date: Apr 30, 2026 2:02:34 PM
Created Date: Apr 30, 2026 2:02:21 PM
Overdue on: Jul 02, 2026 2:02:21 PM
Closed on:

Location: 2934 STRANDEN RD, Baltimore City,
21230

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		4/30/2026 2:02 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3040210
Assign inspector	LLC / POLE #	7136
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-4-30-26	Gregory Crowder	4/30/2026 2:04 PM	Private