

Inspections: Damaged Pole Report

Service Request: 26-00397818 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: Washington Blvd at W. Patapsco Ave
 Grid : 30 30 330 LLC: 7030

Descriptive Location and Comments:

Street: Washington Blvd
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: W. Patapsco


Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Mill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Need new Pedestal Base

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Mill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	_____	Metal ☒
No _____	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 4/30/2026 Inspector's Signature: G. Crowder 8512



3724-US 1

W. Patapsco Ave @ Washington Blvd

Service Request Summary Report
26-00397818
Printed Date: Apr 30, 2026 - 1:57:13 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00397818
Priority: Standard
Status: Pending
Status Date: Apr 30, 2026 1:53:27 PM
Created Date: Apr 30, 2026 1:53:04 PM
Overdue on: Jul 02, 2026 1:53:04 PM
Closed on:

Location: WASHINGTON BLVD & W PATAPSCO AVE, Baltimore City,
21230

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		4/30/2026 1:53 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3030330
Assign inspector	LLC / POLE #	7030
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Pedestal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report by G Crowder-4-30-26	Gregory Crowder	4/30/2026 1:56 PM	Private