

Inspections: Damaged Pole Report

Service Request: 26-00399876 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 2502 W. Northern Pkwy
 Grid : 1050440 LLC: 7234

Descriptive Location and Comments:

Street: W. Northern Pkwy
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O _____ S/O _____ W/O ☒
 Street or Landmark: Pimlico Rd

Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide ☒	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

Pedestal Base: _____ Base Condition: Good _____ Bad: _____ Base Type: _____
 Yes ☒ No ☒ Bolts ☒ Wires ☒ Conduit ☒ Metal ☒ Concrete ☒

Date: 5/4/2026 Inspector's Signature: G. Crowder 8512



341253

30 ft CHCED

Thurs a Friday

1050440

7234

Service Request Summary Report**26-00399876**

Printed Date: May 4, 2026 - 3:48:00 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Fitzgerald
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00399876
Priority: Urgent
Status: Pending
Status Date: May 04, 2026 3:47:52 PM
Created Date: May 01, 2026 7:42:12 AM
Overdue on: Jul 03, 2026 2:16:26 PM
Closed on:

Location: 2502 W NORTHERN PKWY, Baltimore City,
21215

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		5/4/2026 3:44 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1050440
Assign inspector	LLC / POLE #	7234
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-5-4-26	Gregory Crowder	5/4/2026 3:47 PM	Private