

Sent 2 Chms 5/28/26
Watt

Inspections: Damaged Pole Report

Service Request: 26-00479551 Sector: 3 Gateway: _____ Primary: _____
Location on Service Request: 4368 Old Frederick Rd
Grid : 3010 430 LLC: 5008

Descriptive Location and Comments:

Street: Old Frederick
Side of Street: N/S _____ E/S _____ S/S _____ W/S _____
Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O _____ S/O _____ W/O _____
Street or Landmark: Camellia PL

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

11'6" ☒
12' ☒
25' _____
30' _____
40' _____
Other _____

Aluminum _____
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland ☒
Wooden _____
Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn ☒
Other _____

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

6' _____
10' _____
15' _____
20' _____
Other _____

Damaged _____
Missing _____

Pedestal Base:

Base Condition:

Good

Base Type:

Yes _____
No ☒

Bolts _____
Wires ☒
Conduit ☒

Metal _____
Concrete ☒

Date: 5/27/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report
26-00479551
Printed Date: May 28, 2026 - 4:17:16 PM

Type: BGE-StLight Pole Installation
Created By: Patricia Jones
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00479551
Priority: Urgent
Status: Pending
Status Date: May 28, 2026 4:14:13 PM
Created Date: May 24, 2026 2:52:09 PM
Overdue on: Jul 28, 2026 3:28:42 PM
Closed on:

Location: 4368 OLD FREDERICK RD, Baltimore City, 21229

Location Details:

Description: pole number 5008 and 4368 old frederick road

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
annon annon			

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		5/28/2026 4:14 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010430
Assign inspector	LLC / POLE #	5008
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Homeland Plc
Assign inspector	Type of Fixture	Acorn
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-5-28-26	Gregory Crowder	5/28/2026 4:16 PM	Private