

Sent 2 Chms 6-1-26

Inspections: Damaged Pole Report

Service Request: 26-00496682 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 2668 Lauretta Ave
Grid : 3010 320 LLC: 7165

Descriptive Location and Comments:

Street: Lauretta Ave
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O ☒ S/O _____ W/O _____
Street or Landmark: Ashburton St

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

11'6" ☒
12' _____
25' _____
30' _____
40' _____
Other _____

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____
PMA ☒
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

HPS Vapor ☒
Mercury Vapor _____
Metal Halide _____
LED _____
Other _____

100 _____
150 ☒
175 _____
200 _____
250 _____
400 _____
1000 _____

6' _____
10' _____
15' _____
20' _____
Other _____

Damaged _____
Missing _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:


Yes _____
No ☒

Bolts _____
Wires _____
Conduit _____

☒
☒
☒

Metal ☒
Concrete _____

Date: 6 / 1 / 2026 Inspector's Signature: G. Crowder 8512



Service Request Summary Report**26-00496682**

Printed Date: Jun 1, 2026 - 3:09:37 PM

Type: BGE-StLight Pole Installation
Created By: Kemi Streeter
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00496682
Priority: Urgent
Status: Pending
Status Date: Jun 01, 2026 3:09:28 PM
Created Date: May 29, 2026 2:12:29 PM
Overdue on: Jul 31, 2026 6:59:39 AM
Closed on:

Location: 2668 LAURETTA AVE, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/1/2026 3:05 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010320
Assign inspector	LLC / POLE #	7165
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report Created by G crowder 6-1-26	Gregory Crowder	6/1/2026 3:08 PM	Private