

# Inspections: Damaged Pole Report

Service Request: 26-00522574 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_  
 Location on Service Request: 1900 W. Franklin St  
 Grid : 3010 210 LLC: 7491

## Descriptive Location and Comments:

Street: W. Franklin St  
 Side of Street: N/S \_\_\_\_\_ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_  
 Pole location: 1<sup>st</sup> \_\_\_\_\_ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_  
 Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O \_\_\_\_\_  
 Street or Landmark: N. Monroe St


| Condition of Pole:                               | Pole Size :                             | Type of Pole:                                |
|--------------------------------------------------|-----------------------------------------|----------------------------------------------|
| Deteriorated <input checked="" type="checkbox"/> | 11'6" _____                             | Aluminum <input checked="" type="checkbox"/> |
| Missing <input checked="" type="checkbox"/>      | 12' _____                               | Steel _____                                  |
| Damaged _____                                    | 25' <input checked="" type="checkbox"/> | Galvanized Steel _____                       |
| Arm/Fixture Missing _____                        | 30' _____                               | Fiberglass _____                             |
| Other _____                                      | 40' _____                               | Bolton Hill _____                            |
|                                                  | Other _____                             | Otterbein _____                              |
|                                                  |                                         | Homeland _____                               |
|                                                  |                                         | Wooden _____                                 |
|                                                  |                                         | Other _____                                  |

Need new base

| Fixture Type:                                  | Lamp Type:                                       | Wattage:                                | Arm:                                   | Arm Condition: |
|------------------------------------------------|--------------------------------------------------|-----------------------------------------|----------------------------------------|----------------|
| Cobra Head <input checked="" type="checkbox"/> | HPS Vapor _____                                  | 100 _____                               | 6' <input checked="" type="checkbox"/> | Damaged _____  |
| PMA _____                                      | Mercury Vapor _____                              | 150 _____                               | 10' _____                              | Missing _____  |
| Otterbein _____                                | Metal Halide <input checked="" type="checkbox"/> | 175 _____                               | 15' _____                              |                |
| Homeland _____                                 | LED _____                                        | 200 _____                               | 20' _____                              |                |
| Bolton Hill _____                              | Other _____                                      | 250 _____                               | Other _____                            |                |
| Victorian Acorn _____                          |                                                  | 400 <input checked="" type="checkbox"/> |                                        |                |
| Other _____                                    |                                                  | 1000 _____                              |                                        |                |

| Pedestal Base:                          | Base Condition:                             | Good                                | Bad:  | Base Type:                                |
|-----------------------------------------|---------------------------------------------|-------------------------------------|-------|-------------------------------------------|
| Yes <input checked="" type="checkbox"/> | Bolts <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> | _____ | Metal <input checked="" type="checkbox"/> |
| No <input checked="" type="checkbox"/>  | Wires <input checked="" type="checkbox"/>   | <input checked="" type="checkbox"/> | _____ | Concrete _____                            |
|                                         | Conduit <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> | _____ |                                           |

Date: 6/5/2026 Inspector's Signature: G. Crowder 8512



China Head asst Pds LFO

**Service Request Summary Report**  
**26-00522574**  
Printed Date: Jun 5, 2026 - 2:13:21 PM

**Type:** BGE-StLight Pole Installation  
**Created By:** Gregory Crowder  
**Service Request Owner:** BGE  
**Method Received:** Internal  
**SLA Detail:** 45 Business Days

**SR #:** 26-00522574  
**Priority:** Standard  
**Status:** Pending  
**Status Date:** Jun 05, 2026 2:12:21 PM  
**Created Date:** Jun 05, 2026 2:10:31 PM  
**Overdue on:** Aug 07, 2026 2:10:31 PM  
**Closed on:**

**Location:** 1900 W FRANKLIN ST, Baltimore City,  
21223  
**Location Details:**  
**Description:**

**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name | Address | Email | Phones/Extensions |
|------|---------|-------|-------------------|
|      |         |       |                   |

**Service Activities**

| Activity Name    | Status      | Assigned To     | Outcome  | Outcome Reason | Finish Date      |
|------------------|-------------|-----------------|----------|----------------|------------------|
| Assign inspector | Complete    | Gregory Crowder | Assigned |                | 6/5/2026 2:12 PM |
| Service Response | Not Started |                 |          |                |                  |

**Resolution Questions**

| Service Activity | Resolution Question       | Resolution Answer   |
|------------------|---------------------------|---------------------|
| Assign inspector | GRID #                    | 3010210             |
| Assign inspector | LLC / POLE #              | 7491                |
| Assign inspector | BGE AS8 Work Order Number |                     |
| Assign inspector | BCRL #                    |                     |
| Assign inspector | BCRL Created date         |                     |
| Assign inspector | Pole type                 | 25 ft Aluminum Pole |
| Assign inspector | Type of Fixture           | Cobrahead           |
| Assign inspector | Wattage of the Fixture    | 400 Watts           |
| Assign inspector | Base type                 | Metal               |

**Comments**

| Comment | Comment By | Created Date | Visibility |
|---------|------------|--------------|------------|
|---------|------------|--------------|------------|

**Related Child Service Requests**

**Related Parent Service Requests**