

Inspections: Damaged Pole Report

Service Request: 26-00540105 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3012 Clifton Ave

Grid : 1016 310 LLC: 2011

Descriptive Location and Comments:

Street: Clifton Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: N. Rosedale Ave

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum ☒

Missing ☒

12' _____

Steel _____

Damaged _____

25' ☒

Galvanized Steel _____

Arm/Fixture Missing _____

30' _____

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head ☒

HPS Vapor _____

100 _____

6' ☒

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED ☒

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 ☒

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes ☒

No ☒

Bolts

Wires

Conduit

☒

☒

☒

Metal

Concrete

☒

Date: 6/10/2026 Inspector's Signature: G. Crowder 8512

Service Request Summary Report**26-00540105**

Printed Date: Jun 10, 2026 - 2:51:43 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00540105
Priority: Standard
Status: Pending
Status Date: Jun 10, 2026 2:47:10 PM
Created Date: Jun 10, 2026 2:42:22 PM
Overdue on: Aug 12, 2026 2:42:22 PM
Closed on:

Location: 3012 CLIFTON AVE, Baltimore City,
21216

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		6/10/2026 2:47 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1010310
Assign inspector	LLC / POLE #	7011
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-6-10-26	Gregory Crowder	6/10/2026 2:51 PM	Private