

Call Frank need Pole Pick

Inspections: Damaged Pole Report

Service Request: 26-00604738 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 120 E. 25th
Grid: 2020130 LLC: 7458

Descriptive Location and Comments:

Street: E. 25th St
Side of Street: N/S _____ E/S _____ S/S _____ W/S _____
Pole location: 1st _____ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction: N/O _____ E/O _____ S/O _____ W/O _____
Street or Landmark: N. Calvert St

<u>Condition of Pole:</u>	<u>Pole Size:</u>	<u>Type of Pole:</u>
Deteriorated _____	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' ☒	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn _____		400 ☒		
Other _____		1000 _____		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes ☒	Bolts _____	_____	_____	Metal _____
No ☒	Wires _____	_____	_____	Concrete ☒
	Conduit _____	_____	_____	

Date: 6 / 30 / 2026 Inspector's Signature: G. Crowder 8512

There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

20201307458

REPORT THIS LIGHT



REPORT THIS LIGHT

Service Request Summary Report
26-00604738
Printed Date: Jul 1, 2026 - 7:48:26 AM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00604738
Priority: Standard
Status: Pending
Status Date: Jul 01, 2026 7:41:23 AM
Created Date: Jun 30, 2026 5:55:45 AM
Overdue on: Sep 01, 2026 3:41:38 PM
Closed on:

Location: 120 E 25TH ST, Baltimore City, 21218
Location Details: Pole down on sidewalk
Description: pole is down on sidewalk. Please remove downed pole and replace pole/streetlight. thank you!

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Charles Village Civic Association CVCA		kevinmacartney@yahoo.com	

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		7/1/2026 7:46 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	2020130
Assign inspector	LLC / POLE #	7458
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Concrete

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-6-30-26	Gregory Crowder	7/1/2026 7:48 AM	Private
Assign inspector : missing pole report created by G	Gregory Crowder	7/1/2026 7:48 AM	Public