

Seat 2 Chis 7/14/26
Waiting on Work order

Inspections: Damaged Pole Report

Service Request: 26-00639619 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 124 W Franklin St
Grid: 3010120 LLC: 6390

Descriptive Location and Comments:

Street: W Franklin St
Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction: N/O _____ E/O ☒ S/O _____ W/O _____
Street or Landmark: PARK Ave

<u>Condition of Pole:</u>	<u>Pole Size:</u>	<u>Type of Pole:</u>
Deteriorated _____	11'6" _____	Aluminum _____
Missing ☒	12' ☒	Steel _____
Damaged _____	25' _____	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein ☒
		Homeland _____
		Wooden _____
		Other _____

<u>Fixture Type:</u>	<u>Lamp Type:</u>	<u>Wattage:</u>	<u>Arm:</u>	<u>Arm Condition:</u>
Cobra Head _____	HPS Vapor ☒	100 _____	6' _____	Damaged _____
PMA _____	Mercury Vapor _____	150 ☒	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED _____	200 _____	20' _____	
Bolton Hill _____	Other _____	250 _____	Other _____	
Victorian Acorn ☒		400 _____		
Other _____		1000 _____		

<u>Pedestal Base:</u>	<u>Base Condition:</u>	<u>Good</u>	<u>Bad:</u>	<u>Base Type:</u>
Yes ☒	Bolts ☒	☒	_____	Metal ☒
No _____	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 7/13/2026 Inspector's Signature: G. Crowder 8512



Cathedral St

Cathedral St

W Hamilton St

W Hamilton St

W Hamilton St

W Hamilton St

Park Ave

W Franklin St

Library Ct

Park Ave

Wilson Alley

Service Request Summary Report**26-00639619**

Printed Date: Jul 13, 2026 - 6:51:58 AM

Type: BGE-StLight Pole Installation
Created By: Camille Lecato
Service Request Owner: BGE
Method Received: Phone
SLA Detail: 45 Business Days

SR #: 26-00639619
Priority: Urgent
Status: Open
Status Date: Jul 13, 2026 6:51:53 AM
Created Date: Jul 09, 2026 8:11:16 PM
Overdue on: Sep 11, 2026 3:15:25 PM
Closed on:

Location: 124 W FRANKLIN ST, Baltimore City,
21201

Location Details:

Description: small light pole down on the sidewalk across the street from the location

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Not Started				
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
------------------	---------------------	-------------------

Comments

Comment	Comment By	Created Date	Visibility
---------	------------	--------------	------------

Related Child Service Requests**Related Parent Service Requests****Transfer Parent Service Requests**

TRM-StLight Damaged/Knocked Down/Rusted 26-00642896 Closed (Transferred) 124 W FRANKLIN ST, Baltimore City, 21201

Questions	Answers
Is the pole wooden or metal?	Metal
What is the problem with the street light pole?	Down
Where is the exact location of the pole?	Front of address
Did you witness how the pole was damaged?	No
Is this BGE or City maintained?	BGE