

Inspections: Damaged Pole Report

Service Request: 26-00685 213 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 4342 Cedar Garden Rd
 Grid : 3020430 LLC: 7072

Descriptive Location and Comments:

Street: Cedar Garden Rd
 Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: Bethnal Rd

Condition of Pole:

Deteriorated _____
 Missing ☒
 Damaged _____
 Arm/Fixture Missing _____
 Other _____

Pole Size :

11'6" _____
 12' ☒
 25' _____
 30' _____
 40' _____
 Other _____

Type of Pole:

Aluminum ☒
 Steel _____
 Galvanized Steel _____
 Fiberglass _____
 Bolton Hill _____
 Otterbein _____
 Homeland _____
 Wooden _____
 Other _____

Need new base

Fixture Type:

Cobra Head _____
 PMA ☒
 Otterbein _____
 Homeland _____
 Bolton Hill _____
 Victorian Acorn _____
 Other _____

Lamp Type:

HPS Vapor _____
 Mercury Vapor _____
 Metal Halide _____
 LED ☒
 Other _____

Wattage:

100 _____
 150 ☒
 175 _____
 200 _____
 250 _____
 400 _____
 1000 _____

Arm:

6' _____
 10' _____
 15' _____
 20' _____
 Other _____

Arm Condition:

Damaged _____
 Missing _____

Pedestal Base:

Yes _____
 No ☒

Base Condition:

Bolts ☒
 Wires ☒
 Conduit ☒

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
 Concrete _____

Date: 7/24/2026 Inspector's Signature: G. Crowder - 8512



There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, expose electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

30204307072

REPORT THIS LIGHT

Service Request Summary Report
26-00685213

Printed Date: Jul 24, 2026 - 1:57:39 PM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: API
SLA Detail: 45 Business Days

SR #: 26-00685213
Priority: Urgent
Status: Pending
Status Date: Jul 24, 2026 1:50:02 PM
Created Date: Jul 23, 2026 8:23:02 AM
Overdue on: Sep 24, 2026 3:25:54 PM
Closed on:

Location: 4334 CEDARGARDEN RD, Baltimore City, 21229

Location Details:

Description: On the corner cedargarden Rd andBethany

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Shawn McClain		smccclai2003@hotmail.com	+1 (443) 531-6568

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		7/24/2026 1:50 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020430
Assign inspector	LLC / POLE #	7072
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	12 ft Steel/Aluminum Pole
Assign inspector	Type of Fixture	PMA
Assign inspector	Wattage of the Fixture	150 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-7-24-26	Gregory Crowder	7/24/2026 1:51 PM	Private
Assign inspector : missing pole report created by G	Gregory Crowder	7/24/2026 1:51 PM	Public