

Property Damage Photo Evidence

Claim No.: 26-00693703

Property: 924 N. Luzerne Avenue, Baltimore, Maryland

Contractor: Stella May Contracting

Date photographed: August 6, 2026

Four selected photographs documenting street excavation, heavy machinery positioned directly on the sidewalk, and visible concrete damage and cracking near the property.

Prepared for submission with the property-damage claim.



Photo 1 - Heavy tracked machinery positioned directly on the sidewalk at the edge of the excavation.



Photo 2 - Close-up showing the machinery track beside cracked and broken concrete.



Photo 3 - Machinery positioned across the sidewalk beside visible cracking and patching.



Photo 4 - Wider view of the street excavation, removed pavement, workers, and heavy machinery.