

Waiting on BCE 8/31/24
For LLC # sent Email
to Kevin

Inspections: Damaged Pole Report

Service Request: 2600011904 Sector: _____ Gateway: _____ Primary: _____
Location on Service Request: 2600 Lehman St
Grid : 3020 320 LLC: 7253

Descriptive Location and Comments:

Street: Millington Ave
Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____
Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
Direction : N/O _____ E/O ☒ S/O _____ W/O _____
Street or Landmark: Lehman

Condition of Pole:

Deteriorated _____
Missing ☒
Damaged _____
Arm/Fixture Missing _____
Other _____

Pole Size :

11'6" _____
12' _____
25' ☒
30' _____
40' _____
Other _____

Type of Pole:

Aluminum ☒
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

Need to get LLC #

Fixture Type:

Cobra Head ☒
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

Lamp Type:

HPS Vapor _____
Mercury Vapor _____
Metal Halide _____
LED ☒
Other _____

Wattage:

100 _____
150 _____
175 _____
200 _____
250 _____
400 ☒
1000 _____

Arm:

6' _____
10' _____
15' _____
20' _____
Other _____

Arm Condition:

Damaged _____
Missing _____

Pedestal Base:

Yes _____
No ☒

Base Condition:

Bolts _____
Wires _____
Conduit _____

Good


☒
☒
☒

Bad:

Base Type:

Metal ☒
Concrete _____

Date: 1 / 6 / 2025 Inspector's Signature: G. Crowder 8512



Service Request Summary Report**26-00011904**

Printed Date: Sep 8, 2026 - 7:47:07 AM

Type: BGE-StLight Pole Installation
Created By: citizen Site Guest User
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00011904
Priority: Standard
Status: Pending
Status Date: Aug 31, 2026 1:33:12 PM
Created Date: Jan 06, 2026 1:24:25 PM
Overdue on: Mar 11, 2026 3:56:46 PM
Closed on:

Location: 2600 LEHMAN ST, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions
Eddie Beasley		ebeasley10@gmail.com	+1 (410) 302-5181

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		8/31/2026 1:31 PM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3020320
Assign inspector	LLC / POLE #	7253
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Waiting on information from BGE for pole number	Gregory Crowder	8/31/2026 1:33 PM	Private
Assign inspector : Waiting on information from BGE for	Gregory Crowder	8/31/2026 1:33 PM	Public