

Inspections: Damaged Pole Report

Service Request: 26-00851754 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 3100 Wylie Ave

Grid : 1040 330 LLC: 2078

Descriptive Location and Comments:

Street: Wylie Ave

Side of Street: N/S ☒ E/S _____ S/S _____ W/S _____

Pole location: 1st _____ 2nd ☒ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ☒ S/O _____ W/O _____

Street or Landmark: PARK Hgts Ave

Condition of Pole:

Deteriorated _____

Missing ☒

Damaged _____

Arm/Fixture Missing _____

Other _____

Pole Size :

11'6" _____

12' _____

25' ☒

30' _____

40' _____

Other _____

Type of Pole:

Aluminum ☒

Steel _____

Galvanized Steel _____

Fiberglass _____

Bolton Hill _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need new base

Fixture Type:

Cobra Head ☒

PMA _____

Otterbein _____

Homeland _____

Bolton Hill _____

Victorian Acorn _____

Other _____

Lamp Type:

HPS Vapor _____

Mercury Vapor _____

Metal Halide _____

LED ☒

Other _____

Wattage:

100 _____

150 _____

175 _____

200 _____

250 _____

400 ☒

1000 _____

Arm:

6' ☒

10' _____

15' _____

20' _____

Other _____

Arm Condition:

Damaged _____

Missing _____

Pedestal Base:

Yes ☒

No _____

Base Condition:

Good ☒

Bad: _____

Base Type:

Metal ☒

Concrete _____

Date: 9/8/2026 Inspector's Signature: G. Crowder 8512



There are no known outages for this light.

DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Pole Number

10403307078

REPORT THIS LIGHT

Service Request Summary Report
26-00851754
Printed Date: Sep 9, 2026 - 8:04:03 AM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00851754
Priority: Standard
Status: Pending
Status Date: Sep 09, 2026 8:03:52 AM
Created Date: Sep 09, 2026 7:47:57 AM
Overdue on: Nov 11, 2026 6:47:57 AM
Closed on:

Location: 3100 BLK WYLIE AVE, Baltimore City, 21215

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete		Assigned		9/9/2026 8:02 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1040330
Assign inspector	LLC / POLE #	7078
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : missing pole report created by G Crowder-9-8-26	Gregory Crowder	9/9/2026 8:03 AM	Private
Assign inspector : missing pole report created by G	Gregory Crowder	9/9/2026 8:03 AM	Public