

Inspections: Damaged Pole Report

Service Request: 26-00859103 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: 42 S. Franklinton Rd
 Grid : 3010 340 LLC: 7147

Descriptive Location and Comments:

Street: S. Franklinton Rd
 Side of Street: N/S _____ E/S _____ S/S _____ W/S ☒
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O ☒ E/O _____ S/O _____ W/O _____
 Street or Landmark: Hollins Mt


Condition of Pole:	Pole Size :	Type of Pole:
Deteriorated ☒	11'6" _____	Aluminum ☒
Missing ☒	12' _____	Steel _____
Damaged _____	25' ☒	Galvanized Steel _____
Arm/Fixture Missing _____	30' _____	Fiberglass _____
Other _____	40' _____	Bolton Hill _____
	Other _____	Otterbein _____
		Homeland _____
		Wooden _____
		Other _____

Fixture Type:	Lamp Type:	Wattage:	Arm:	Arm Condition:
Cobra Head ☒	HPS Vapor _____	100 _____	6' ☒	Damaged _____
PMA _____	Mercury Vapor _____	150 _____	10' _____	Missing _____
Otterbein _____	Metal Halide _____	175 _____	15' _____	
Homeland _____	LED ☒	200 ☒	20' _____	
Bolton Hill _____	Other _____	250 ☒	Other _____	
Victorian Acorn _____		400 _____		
Other _____		1000 _____		

Pedestal Base:	Base Condition:	Good	Bad:	Base Type:
Yes ☒	Bolts ☒	☒	_____	Metal ☒
No ☒	Wires ☒	☒	_____	Concrete _____
	Conduit ☒	☒	_____	

Date: 9/10/2026 Inspector's Signature: E. Crowder 8512

25ft LED Can Head



Service Request Summary Report
26-00859103
Printed Date: Sep 10, 2026 - 3:58:30 PM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00859103
Priority: Standard
Status: Pending
Status Date: Sep 10, 2026 3:47:03 PM
Created Date: Sep 10, 2026 3:33:13 PM
Overdue on: Nov 12, 2026 2:33:13 PM
Closed on:

Location: 42 S FRANKLINTOWN RD, Baltimore City,
21223

Location Details:
Description:

Service Questions

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		9/10/2026 3:48 PM
Service Response	Complete		Outcome		9/10/2026 3:40 PM

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	3010340
Assign inspector	LLC / POLE #	7147
Assign inspector	BGE AS8 Work Order Number	
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	25 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	Other
Assign inspector	Base type	Metal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : waiting on BGE for Grid And pole number	Gregory Crowder	9/10/2026 3:49 PM	Private
Assign inspector : waiting on BGE for Grid And pole	Gregory Crowder	9/10/2026 3:49 PM	Public