

# Inspections: Damaged Pole Report

Service Request: 26-00881437 Sector: \_\_\_\_\_ Gateway: \_\_\_\_\_ Primary: \_\_\_\_\_  
 Location on Service Request: 2102 Chelsea Terr  
 Grid : 1016420 LLC: 7094

## Descriptive Location and Comments:

Street: Chelsea Terr  
 Side of Street: N/S ☒ E/S \_\_\_\_\_ S/S \_\_\_\_\_ W/S \_\_\_\_\_  
 Pole location: 1<sup>st</sup> ☒ 2<sup>nd</sup> \_\_\_\_\_ 3<sup>rd</sup> \_\_\_\_\_ 4<sup>th</sup> \_\_\_\_\_ 5<sup>th</sup> \_\_\_\_\_ 6<sup>th</sup> \_\_\_\_\_ Other \_\_\_\_\_  
 Direction : N/O \_\_\_\_\_ E/O \_\_\_\_\_ S/O \_\_\_\_\_ W/O ☒  
 Street or Landmark: Clifton Ave

## Condition of Pole:

Deteriorated \_\_\_\_\_  
 Missing ☒  
 Damaged \_\_\_\_\_  
 Arm/Fixture Missing \_\_\_\_\_  
 Other \_\_\_\_\_

## Pole Size :

11'6" \_\_\_\_\_  
 12' \_\_\_\_\_  
 25' ☒  
 30' \_\_\_\_\_  
 40' \_\_\_\_\_  
 Other \_\_\_\_\_

## Type of Pole:

Aluminum ☒  
 Steel \_\_\_\_\_  
 Galvanized Steel \_\_\_\_\_  
 Fiberglass \_\_\_\_\_  
 Bolton Hill \_\_\_\_\_  
 Otterbein \_\_\_\_\_  
 Homeland \_\_\_\_\_  
 Wooden \_\_\_\_\_  
 Other \_\_\_\_\_

*Need new base*

## Fixture Type:

Cobra Head ☒  
 PMA \_\_\_\_\_  
 Otterbein \_\_\_\_\_  
 Homeland \_\_\_\_\_  
 Bolton Hill \_\_\_\_\_  
 Victorian Acorn \_\_\_\_\_  
 Other \_\_\_\_\_

## Lamp Type:

HPS Vapor \_\_\_\_\_  
 Mercury Vapor \_\_\_\_\_  
 Metal Halide \_\_\_\_\_  
 LED ☒  
 Other \_\_\_\_\_

## Wattage:

100 \_\_\_\_\_  
 150 \_\_\_\_\_  
 175 \_\_\_\_\_  
 200 \_\_\_\_\_  
 250 \_\_\_\_\_  
 400 ☒  
 1000 \_\_\_\_\_

## Arm:

6' ☒  
 10' \_\_\_\_\_  
 15' \_\_\_\_\_  
 20' \_\_\_\_\_  
 Other \_\_\_\_\_

## Arm Condition:

Damaged \_\_\_\_\_  
 Missing \_\_\_\_\_

## Pedestal Base:

Yes \_\_\_\_\_  
 No \_\_\_\_\_

## Base Condition:

Bolts ☒  
 Wires ☒  
 Conduit ☒

## Good

☒  
☒  
☒

## Bad:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

## Base Type:

Metal ☒  
 Concrete \_\_\_\_\_

Date: 9/13/2026 Inspector's Signature: J. Crowder - 8512

We are aware of a problem on this streetlight.

Status:

Pending Repair

Pole Number:

10104207094

Order Number:

20871543

Date Reported:

3/16/2026 7:47 AM EDT

Estimated Time of Repair:

04/10/2026


**DOWNED POLE & EXPOSED WIRES**

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

**NEVER TOUCH EXPOSED WIRES!**

Subscribe to Incident Alerts

Enter your email. For multiple emails, separate with semicolon (;).



**Service Request Summary Report**  
**26-00881437**  
Printed Date: Sep 17, 2026 - 7:49:47 AM

**Type:** BGE-StLight Pole Installation  
**Created By:** Gregory Crowder  
**Service Request Owner:** BGE  
**Method Received:** Internal  
**SLA Detail:** 45 Business Days

**SR #:** 26-00881437  
**Priority:** Standard  
**Status:** Pending  
**Status Date:** Sep 17, 2026 7:47:37 AM  
**Created Date:** Sep 17, 2026 7:45:32 AM  
**Overdue on:** Nov 19, 2026 6:45:32 AM  
**Closed on:**

**Location:** 2102 CHELSEA TER, Baltimore City,  
21216

**Location Details:**  
**Description:**

**Service Questions**

| Questions | Answers |
|-----------|---------|
|-----------|---------|

**Contact Information**

| Name | Address | Email | Phones/Extensions |
|------|---------|-------|-------------------|
|      |         |       |                   |

**Service Activities**

| Activity Name    | Status      | Assigned To     | Outcome  | Outcome Reason | Finish Date       |
|------------------|-------------|-----------------|----------|----------------|-------------------|
| Assign inspector | Complete    | Gregory Crowder | Assigned |                | 9/17/2026 7:47 AM |
| Service Response | Not Started |                 |          |                |                   |

**Resolution Questions**

| Service Activity | Resolution Question       | Resolution Answer   |
|------------------|---------------------------|---------------------|
| Assign inspector | GRID #                    | 1010420             |
| Assign inspector | LLC / POLE #              | 7094                |
| Assign inspector | BGE AS8 Work Order Number | 20871543            |
| Assign inspector | BCRL #                    |                     |
| Assign inspector | BCRL Created date         |                     |
| Assign inspector | Pole type                 | 25 ft Aluminum Pole |
| Assign inspector | Type of Fixture           | Cobrahead           |
| Assign inspector | Wattage of the Fixture    | 400 Watts           |
| Assign inspector | Base type                 | Metal               |

**Comments**

| Comment                                                             | Comment By      | Created Date      | Visibility |
|---------------------------------------------------------------------|-----------------|-------------------|------------|
| Assign inspector : missing pole report created by G Crowder-9-13-26 | Gregory Crowder | 9/17/2026 7:49 AM | Private    |
| Assign inspector : missing pole report created by G                 | Gregory Crowder | 9/17/2026 7:49 AM | Public     |