## Inspections: Damaged Pole Report

Service Request: 26-00803823 Sector: _____ Gateway: _____ Primary: _____

Location on Service Request: 2555 Mc Henry St

Grid : 3010340 LLC: 7326

**Descriptive Location and Comments:**

Street: Mc Henry St

Side of Street: N/S _____ E/S ✓ S/S _____ W/S _____

Pole location: 1st ✓ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____

Direction : N/O _____ E/O ✓ S/O _____ W/O _____

Street or Landmark: S. Franklinton Rd

**Condition of Pole:**

Deteriorated _____
Missing ✓
Damaged _____
Arm/Fixture Missing _____
Other _____

**Pole Size :**

11'6" _____
12' _____
25' ✓
30' _____
40' _____
Other _____

**Type of Pole:**

Aluminum ✓
Steel _____
Galvanized Steel _____
Fiberglass _____
Bolton Hill _____
Otterbein _____
Homeland _____
Wooden _____
Other _____

**Fixture Type:**

Cobra Head ✓
PMA _____
Otterbein _____
Homeland _____
Bolton Hill _____
Victorian Acorn _____
Other _____

**Lamp Type:**

HPS Vapor _____
Mercury Vapor _____
Metal Halide ✓
LED _____
Other _____

**Wattage:**

100 _____
150 _____
175 _____
200 _____
250 _____
400 ✓
1000 _____

**Arm:**

6' ✓
10' _____
15' _____
20' _____
Other _____

**Arm Condition:**

Damaged _____
Missing _____

**Pedestal Base:**

Yes _____
No ✓

**Base Condition:**

| | Good | Bad: |
|---|---|---|
| Bolts | ✓ | _____ |
| Wires | ✓ | _____ |
| Conduit | ✓ | _____ |

**Base Type:**

Metal ✓
Concrete _____

Date: 9/17/2026 Inspector's Signature G. Crowder 8512

Hafer St
S Franklintown Rd
S Franklintown Rd
S Franklintown Rd
S Franklintown Rd
McHenry St
McHenry St
McHenry St
McHenry St
Maempel Ln
2555
2553
2551
2549
2547
2541
2539
2537
2527
2525
305
307
309
311
313
315
317
310
312
300
220

**Service Request Summary Report**
**26-00863823**
Printed Date: Sep 15, 2026 - 10:54:30 AM

| | | | |
|---|---|---|---|
| **Type:** | BGE-StLight Pole Installation | **SR #:** | 26-00863823 |
| **Created By:** | Adrienne Coner | **Prority:** | Urgent |
| **Service Request Owner:** | BGE | **Status:** | Open |
| **Method Received:** | Phone | **Status Date:** | Sep 15, 2026 10:54:23 AM |
| **SLA Detail:** | 45 Business Days | **Created Date:** | Sep 11, 2026 9:33:55 PM |
| | | **Overdue on:** | Nov 16, 2026 2:21:14 PM |
| | | **Closed on:** | |
| **Location:** | 2549 MCHENRY ST, Baltimore City, 21223 | | |
| **Location Details:** | | | |
| **Description:** | pole is knocked down and the base is covered with a cone due to wires being exposed and sparkling | | |

**Service Questions**

| Questions | Answers |
|---|---|

**Contact Information**

| Name | Address | Email | Phones/Extensions |
|---|---|---|---|
| unique garett | | bmoreofaqueen@gmail.com | +1 (443) 404-6453 |

**Service Activities**

| Activity Name | Status | Assigned To | Outcome | Outcome Reason | Finish Date |
|---|---|---|---|---|---|
| Assign inspector | Not Started | | | | |
| Service Response | Not Started | | | | |

**Resolution Questions**

| Service Activity | Resolution Question | Resolution Answer |
|---|---|---|

**Comments**

| Comment | Comment By | Created Date | Visibility |
|---|---|---|---|

**Related Child Service Requests**

**Related Parent Service Requests**

**Transfer Parent Service Requests**

| | | | |
|---|---|---|---|
| **TRM-StLight Damaged/Knocked Down/Rusted** | **26-00870934** | **Closed (Transferred)** | **2549 MCHENRY ST, Baltimore City, 21223** |

| Questions | Answers |
|---|---|
| Is the pole wooden or metal? | Metal |
| What is the problem with the street light pole? | Down |
| Where is the exact location of the pole? | |
| Did you witness how the pole was damaged? | No |
| Is this BGE or City maintained? | BGE |