

Inspections: Damaged Pole Report

W0# 20251930

Service Request: 26-00 897 346 Sector: _____ Gateway: _____ Primary: _____
 Location on Service Request: N. Warwick Ave at Hargraves Falls Pkwy
 Grid : 1020 340 LLC: 7062

Descriptive Location and Comments:

Street: Hargraves Falls Pkwy
 Side of Street: N/S _____ E/S _____ S/S ☒ W/S _____
 Pole location: 1st ☒ 2nd _____ 3rd _____ 4th _____ 5th _____ 6th _____ Other _____
 Direction : N/O _____ E/O ☒ S/O _____ W/O _____
 Street or Landmark: N. Warwick

Condition of Pole:

Pole Size :

Type of Pole:

Deteriorated _____

11'6" _____

Aluminum _____

Missing ☒

12' _____

Steel _____

Damaged _____

25' _____

Galvanized Steel _____

Arm/Fixture Missing _____

30' ☒

Fiberglass _____

Other _____

40' _____

Bolton Hill _____

Other _____

Otterbein _____

Homeland _____

Wooden _____

Other _____

Need New Pedestal Base

Fixture Type:

Lamp Type:

Wattage:

Arm:

Arm Condition:

Cobra Head _____

HPS Vapor _____

100 _____

6' _____

Damaged _____

PMA _____

Mercury Vapor _____

150 _____

10' _____

Missing _____

Otterbein _____

Metal Halide _____

175 _____

15' _____

Homeland _____

LED _____

200 _____

20' _____

Bolton Hill _____

Other _____

250 _____

Other _____

Victorian Acorn _____

400 _____

Other _____

1000 _____

Pedestal Base:

Base Condition:

Good

Bad:

Base Type:

Yes _____

No _____

Bolts

Wires

Conduit

Metal

Concrete

Date:

1 / 2026

Inspector's Signature

J. Crowder - 8512

We are aware of a problem on this streetlight.

Status:

Pending Repair

Pole Number:

10203407062

Order Number:

20251930

Date Reported:

6/6/2025 9:44 AM EDT

Estimated Time of Repair:

07/01/2025


DOWNED POLE & EXPOSED WIRES

If you discover a downed streetlight pole, exposed electrical wires or any other hazardous situation, please call us immediately at **1-800-685-0123** with the closest address, intersection or landmark.

NEVER TOUCH EXPOSED WIRES!

Subscribe to Incident Alerts

Enter your email. For multiple emails, separate with semicolon (;).



Service Request Summary Report**26-00897346**

Printed Date: Sep 22, 2026 - 7:36:07 AM

Type: BGE-StLight Pole Installation
Created By: Gregory Crowder
Service Request Owner: BGE
Method Received: Internal
SLA Detail: 45 Business Days

SR #: 26-00897346
Priority: Standard
Status: Pending
Status Date: Sep 22, 2026 7:30:59 AM
Created Date: Sep 22, 2026 7:30:17 AM
Overdue on: Nov 24, 2026 6:30:17 AM
Closed on:

Location: N WARWICK AVE & GWYNNS FALLS PKWY, Baltimore City,
21217

Location Details:**Description:****Service Questions**

Questions	Answers
-----------	---------

Contact Information

Name	Address	Email	Phones/Extensions

Service Activities

Activity Name	Status	Assigned To	Outcome	Outcome Reason	Finish Date
Assign inspector	Complete	Gregory Crowder	Assigned		9/22/2026 7:33 AM
Service Response	Not Started				

Resolution Questions

Service Activity	Resolution Question	Resolution Answer
Assign inspector	GRID #	1020340
Assign inspector	LLC / POLE #	7062
Assign inspector	BGE AS8 Work Order Number	20251930
Assign inspector	BCRL #	
Assign inspector	BCRL Created date	
Assign inspector	Pole type	30 ft Aluminum Pole
Assign inspector	Type of Fixture	Cobrahead
Assign inspector	Wattage of the Fixture	400 Watts
Assign inspector	Base type	Pedestal

Comments

Comment	Comment By	Created Date	Visibility
Assign inspector : Missing pole report created G Crowder-9-21-26	Gregory Crowder	9/22/2026 7:36 AM	Private
Assign inspector : Missing pole report created G	Gregory Crowder	9/22/2026 7:36 AM	Public